



Bluetooth[®] compatibility
LS, GS, RX models

LS, GS, RX models

Bluetooth® compatibility

Lexus Bluetooth® Hands-Free system works with Bluetooth® enabled phones supporting the Bluetooth® Hands-Free profile. However, even though a phone supports the Hands-Free profile, it might not be capable of taking advantage of all the advanced features offered by the Lexus Bluetooth® Hands-Free system.

The list provided here describes the level of compatibility of several popular Bluetooth® phones.

The listed phones are tested against 3 categories :

- connection features
- call handling features
- phonebook transfer features

The results of the tests are depicted as follow :

- if the test completed successfully
- ✗ if the test failed

CONNECTIVITY

Connectivity testing assesses the capabilities of each phone to establish a connection with Lexus Hands-Free system :

Pair and connect - Ability of the phone to be linked with Lexus Hands-Free system

Auto connection - Ability of the phone, once registered in Lexus Hands-Free system, to automatically establish connection with the vehicle

PHONEBOOK

Phonebook testing assesses the capabilities of each phone to transfer phonebook data from the phone to the Hands-Free system :

Bulk transfer - Ability of the phone to transfer all of the address book contacts to the Hands-Free system in one single transfer operation

One entry at a time - Ability of the phone to transfer a single address book contact to the Hands-Free system

CALLS

Call handling testing assesses the capabilities of each phone to support incoming and outgoing calls and additional features related to Hands-Free communication :




Incoming call - Ability of the phone to accept or reject an incoming call to the Hands-Free system

Outgoing call - Ability of the phone to place and end an outgoing call from the Hands-Free system













Voice dialling - Ability of the phone to dial a number from the voice dialling interface of the Hands-Free system






Redialling - Ability of the phone to redial the last dialled number

Audio transfer - ability of the phone to transfer a call from the Hands-Free system to the phone and from the phone to the Hands-Free system

Phone			Connectivity		Calls					Phonebook	
Brand	Model	Firmware	Pair and connect	Auto connection	Incoming call	Outgoing call	Voice dialling	Redialling	Audio transfer	Bulk transfer	One entry at a time
Apple	 iPhone	1.1.4	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input checked="" type="checkbox"/>	<input type="radio"/>	<input type="radio"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
BenQ	 EF81	KE_1443_11.0.2	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input checked="" type="checkbox"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>
BlackBerry	 8700v	v4.10.232	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input checked="" type="checkbox"/>	<input type="radio"/>	<input type="radio"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
	 8300 Curve	24.0.31	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input checked="" type="checkbox"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>
	 8100 Pearl	22.0.32	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input checked="" type="checkbox"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>
	 8110 Pearl	4.3.0.93	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input checked="" type="checkbox"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input checked="" type="checkbox"/>
HP	 514	5.2.1237 Build 17742.0.2.2	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input checked="" type="checkbox"/>	<input type="radio"/>	<input type="radio"/>	<input checked="" type="checkbox"/>	<input type="radio"/>
	 6815	5.1.195 Build 14989.2.6.0	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input checked="" type="checkbox"/>	<input type="radio"/>	<input type="radio"/>	<input checked="" type="checkbox"/>	<input type="radio"/>
	 6915	5.1.195 Build 14928.2.2.0	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input checked="" type="checkbox"/>	<input type="radio"/>	<input type="radio"/>	<input checked="" type="checkbox"/>	<input type="radio"/>
HTC	 P3350	5.1.461 Build 15671.3.3.0	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input checked="" type="checkbox"/>	<input type="radio"/>	<input type="radio"/>	<input checked="" type="checkbox"/>	<input type="radio"/>
	 P3600	5.1.465 Build 15673.3.3.1	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input checked="" type="checkbox"/>	<input type="radio"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="radio"/>
	 P4350	5.1.422 Build 15633.3.2.0	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input checked="" type="checkbox"/>	<input type="radio"/>	<input type="radio"/>	<input checked="" type="checkbox"/>	<input type="radio"/>













Phone			Connectivity		Calls					Phonebook	
Brand	Model	Firmware	Pair and connect	Auto connection	Incoming call	Outgoing call	Voice dialling	Redialling	Audio transfer	Bulk transfer	One entry at a time
HTC	 P6300	5.1465 Build 15673.3.3.1	○	○	○	○	✗	○	○	✗	○
	 S620	5.1342 Build 15097.3.0.1	○	○	○	○	✗	○	○	✗	○
	 S710	5.21236 Build 17741.0.2.1	○	○	○	○	✗	○	○	✗	○
	 Touch	5.21238 Build 17745.0.2.3	○	○	○	○	✗	○	○	✗	○
LG	 KE800	KE800P40-EUR-V10g	○	○	○	○	✗	○	○	✗	✗
	 KE850 Prada	KE850P40-EUR-V10n	○	○	○	○	✗	○	○	✗	✗
	 KE970 Shine	KE970P40FL-44-V10d	○	○	○	○	✗	○	○	✗	✗
	 KF600	KF600AT-00-V10b	○	○	○	○	✗	○	○	✗	○
	 KF750 Secret	KG800P64-EUR-V10h	○	○	○	○	✗	○	○	✗	○
	 KG800	KG800P64-EUR-V10h	○	✗	○	✗	✗	○	○	✗	✗
	 KG810	KG810P64 GBR-V10b	○	○	○	○	✗	○	○	✗	✗
	 KS20	5.21437 Build 17944.0.3.1	○	○	○	○	✗	○	○	✗	✗



Phone			Connectivity		Calls					Phonebook	
Brand	Model	Firmware	Pair and connect	Auto connection	Incoming call	Outgoing call	Voice dialling	Redialling	Audio transfer	Bulk transfer	One entry at a time
LG	 KU990 VIEWTY		<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>
Motorola	 KRZR K1	R4527_G_08.2 207R	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>	<input type="radio"/>
	 MOTO Q9h	5.2.1809 (Build 18322.0.6.1)	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>
	 PEBL U6	R478_G_08.84 2DR_A	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>
	 RAZR V3i	R478_G_08.84 2DR_A	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>	<input type="radio"/>
	 RAZR V3x	R252211LD_U_8 5.92.70R	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>
	 RAZR2 V8	R601_G_80.42. 0FR	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>	<input type="radio"/>
	 RAZR2 V9	R263313_U_A0. 03.05R	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>
	 RIZR Z3	R452B_G_08.0 1.05R	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>	<input type="radio"/>
	 SLVR L7	R4513_G_08.B 7.ABR_RB	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>
	 SLVR L9	R452J_G_08.2 2.04R	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input type="radio"/>
	 U9	R6632_G_81.11.1 5I	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>








Phone			Connectivity		Calls					Phonebook	
Brand	Model	Firmware	Pair and connect	Auto connection	Incoming call	Outgoing call	Voice dialling	Redialling	Audio transfer	Bulk transfer	One entry at a time
Motorola	 V360	R4513_G_08.B7.56R_A	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input checked="" type="checkbox"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>
	 W510	R452G_G_08.10.15R	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input checked="" type="checkbox"/>	<input type="radio"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="radio"/>
Nokia	 2630	V 03.82 RM-298	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
	 5300	V03.50 14-09-06 RM-146	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input checked="" type="checkbox"/>	<input type="radio"/>	<input type="radio"/>	<input checked="" type="checkbox"/>	<input type="radio"/>
	 5310	V03.63 24-10-07 RM-303	<input type="radio"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
	 5610	V 04.20 RM-242	<input type="radio"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
	 6120	V03.70	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input checked="" type="checkbox"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>
	 6124 Classic	V 04.34 RM-422	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input checked="" type="checkbox"/>	<input type="radio"/>	<input type="radio"/>	<input checked="" type="checkbox"/>	<input type="radio"/>
	 6151	V04.10 21-12-06 RM-200	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input checked="" type="checkbox"/>	<input type="radio"/>	<input type="radio"/>	<input checked="" type="checkbox"/>	<input type="radio"/>
	 6233	V04.10 21-12-06 RM-200	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input checked="" type="checkbox"/>	<input type="radio"/>	<input type="radio"/>	<input checked="" type="checkbox"/>	<input type="radio"/>
	 6300	v05.50 14-08-07 RM-217	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input checked="" type="checkbox"/>	<input type="radio"/>	<input type="radio"/>	<input checked="" type="checkbox"/>	<input type="radio"/>
	 6500 Classic	V03.2131-08-07	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input checked="" type="checkbox"/>	<input type="radio"/>	<input type="radio"/>	<input checked="" type="checkbox"/>	<input type="radio"/>

Phone			Connectivity		Calls					Phonebook		
Brand	Model	Firmware	Pair and connect	Auto connection	Incoming call	Outgoing call	Voice dialling	Redialling	Audio transfer	Bulk transfer	One entry at a time	
Nokia		7390	V04.5129-11-06 RM-140	○	○	○	○	✗	○	○	✗	○
		8600 Luna	V03.52 24-05-07 RM-164	○	○	○	○	✗	○	○	✗	○
		7500 Prism	V03.50 25-07-07 RM-249	○	○	○	○	✗	○	○	✗	○
		8800 Sirocco	V 03.51RM-165	○	✗	✗	✗	✗	✗	✗	✗	✗
		8800 Sapphire Arte	V05.21 30-11-07 RM-233	○	○	○	○	✗	○	✗	✗	○
		9300i	V05.50(00) 16-12-2005	○	○	○	○	✗	○	○	✗	○
		E51	100.34.20 29-09-2007 RM-244	○	○	○	○	✗	○	○	○	○
		E65	1.0633.18.01 RM-208	○	○	○	○	✗	○	○	○	○
		E90	v07.40.12 03-10-2007 RA-6	○	○	○	○	✗	○	○	✗	○
		N70	V2.0536.0.2 12-09-05	○	○	○	○	✗	○	○	✗	○
		N73	V3.0638.0.0.30 RM-133	○	○	○	○	✗	○	○	✗	○
		N78	0.290 26-02-2008	○	○	○	○	✗	○	○	○	○

Phone			Connectivity		Calls					Phonebook	
Brand	Model	Firmware	Pair and connect	Auto connection	Incoming call	Outgoing call	Voice dialling	Redialling	Audio transfer	Bulk transfer	One entry at a time
Nokia	 N80	V 4.0623.0.42 RM-92	○	○	○	○	✗	○	○	✗	○
	 N81	V01.0716.1.0.09 15-05-07	○	○	○	○	✗	○	○	○	○
	 N82	V20.0.062 28- 02-08 RM-313	✗	✗	✗	✗	✗	✗	✗	✗	✗
	 N95	V11.0.026 17-04- 07	○	○	○	○	✗	○	○	✗	○
Palm	 Treo 500v	V11.0.026 17-04- 07	○	○	○	○	✗	○	○	○	○
	 Treo 650	1.71	✗	✗	✗	✗	✗	✗	✗	✗	✗
	 Treo 680	R01.31	○	○	○	○	✗	○	○	✗	○
	 Treo 750	5.1195 Build 14959.2.3.2	○	○	○	○	✗	○	○	✗	○
Sagem	 MY401	LC5, CJ 35942700900 049 268315175409	○	○	○	○	✗	○	○	✗	✗
	 MY41v	LV5, RP 355150019033 61 210615134578	○	○	○	○	✗	○	✗	○	○
	 MY850		✗	✗	✗	✗	✗	✗	✗	✗	✗
Samsung	 D900	D900iACGE1	✗	✗	✗	✗	✗	✗	✗	✗	✗

Phone			Connectivity		Calls					Phonebook		
Brand	Model	Firmware	Pair and connect	Auto connection	Incoming call	Outgoing call	Voice dialling	Redialling	Audio transfer	Bulk transfer	One entry at a time	
Samsung	 E900	E900ADFF1	○	○	○	○	✗	○	○	✗	✗	
	 F110 miCoach	F110ACGK1	○	○	○	○	○	○	○	✗	○	
	 F300	F300ACGC1	○	○	○	○	✗	○	○	✗	✗	
	 F490	F490ACHA2	○	○	○	○	✗	○	○	✗	✗	
	 G600	G600ACGG3	✗	✗	✗	✗	✗	✗	✗	✗	✗	
	 G800	G800XXG12	✗	✗	✗	✗	✗	✗	✗	✗	✗	
	 i320	I320ACFJ2	✗	✗	✗	✗	✗	✗	✗	✗	✗	
	 i640	i640BUGJ2	○	○	○	○	✗	○	○	✗	○	
	 Steel (L810v)	L810NUHD7	○	○	○	○	○	✗	○	○	○	○
	 U600	U600MSGC4	○	○	○	○	○	✗	○	○	✗	✗
	 X820	X280NXXFJ1	○	○	○	○	✗	✗	○	○	✗	✗
	 X830	X830XXGA2	○	○	○	○	○	✗	○	○	✗	✗

Phone			Connectivity		Calls					Phonebook	
Brand	Model	Firmware	Pair and connect	Auto connection	Incoming call	Outgoing call	Voice dialling	Redialling	Audio transfer	Bulk transfer	One entry at a time
Sharp	 GX33	A02-014-0145-GX33	X	X	X	X	X	X	X	X	X
	 550SH	7.0.2.1.h.1122	X	X	X	X	X	X	X	X	X
Sony Ericsson	 C702i	R3BA030	O	O	O	O	X	O	O	O	O
	 K750i	RICB008	O	O	O	O	X	O	O	O	O
	 K770i	R8AA018	O	O	O	O	X	O	O	O	O
	 K800i	R1KG001	O	O	O	O	X	O	O	X	O
	 K850i	1200-4399 R1CA037 071012	O	O	O	O	X	O	O	X	X
	 P1i	R9J005	O	O	O	O	X	O	O	X	O
	 P990i	R5A006	O	O	O	O	X	O	O	O	O
	 W350i	R10BA015	O	O	O	O	X	O	O	O	O
	 W380i	R9BA023	O	O	O	O	X	O	O	O	O
	 W580i	CXC1123362 R6BC002 070607	O	O	O	O	X	O	O	O	O

Phone			Connectivity		Calls					Phonebook	
Brand	Model	Firmware	Pair and connect	Auto connection	Incoming call	Outgoing call	Voice dialling	Redialling	Audio transfer	Bulk transfer	One entry at a time
Sony Ericsson	 W610i	R1KG001	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input checked="" type="checkbox"/>	<input type="radio"/>	<input type="radio"/>	<input checked="" type="checkbox"/>	<input type="radio"/>
	 W810i	R4DB004	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input checked="" type="checkbox"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>
	 W850i	R1ED001	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input checked="" type="checkbox"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>
	 W880i	R1JC002	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input checked="" type="checkbox"/>	<input type="radio"/>	<input type="radio"/>	<input checked="" type="checkbox"/>	<input type="radio"/>
	 W890i	R1DA028	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input checked="" type="checkbox"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>
	 W910i	R1CA037	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input checked="" type="checkbox"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>
	 W950i	R9F001	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input checked="" type="checkbox"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>
	 W960i	R9J005	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input checked="" type="checkbox"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>
Three	 Skype phone		<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input checked="" type="checkbox"/>	<input type="radio"/>	<input type="radio"/>	<input checked="" type="checkbox"/>	<input type="radio"/>

The information provided above is purely the opinion of Toyota Motor Europe and to the fullest extent permitted by law no warranty representation express or implied is made as to the completeness or accuracy of the information or the compatibility of the products referred to. Neither Toyota Motor Europe nor its officers or affiliates accept liability for any direct or indirect or consequential loss including loss of profit or data arising in connection with the information provided above.

The BLUETOOTH word mark and logos are owned by the BLUETOOTH SIG, Inc and any use of such marks by Toyota Motor Europe is under licence. Other trade marks and trade names are those of their respective owners.